













MaxiSys MS919S2

Packing List

Main Unit		Scope Test Lead 1x4 PCS		Large Dolphin Clip 1x2 PCS	
MaxiFlash VCMII2		Multimeter Test Lead 1x2 PCS		USB to Ethernet Adapter	
USB Type-C Cable		Secondary Ignition Pickup 2 PCS		Quick Reference Guide	
Main Cable V2.0		Breakout Lead 4x6 PCS		Quick Start Guide	
USB 2.0 Cable V2		Multimeter Probe 1x2 PCS		Packing List (This document)	
AC/DC Adapter (12 V)		Flexible Back-pinning Probe 2x2 PCS		Soft Cloth	
Auxiliary Power Outlet Adapter		Back-pinning Probe - Red/Green/ Blue/Yellow/Black 1x5 PCS		Tool Box	
Spare Fuse 6x30mm 2 PCS		Back-pinning Probe Screw 2 PCS		Accessory Storage Bag	
Clamp Cable		Back-pinning Probe Replacement Needle 20 PCS		Carrying Case	
Attenuator 20:1 2 PCS		Small Alligator Clip 2x2 PCS		*Oscilloscope Accessory Kit and Non-OBD II Adapter Kit, each sold separately.	